

TOLERANČNÍ POLE DĚR PRO JMENOVITÉ ROZMĚRY OD 1 DO 500mm

Mezní úchytky

Rozměry (mm)	Toleranční pole																			
										H7	Js7	K7	N7	P7	F8	H8	E9	H9		H11
	H5	Js5	G6	H6	Js6	K6	N6	P6	F7										D11	
	Mezní úchytky(micro m)																			
od 1 do 3	+4	+2,0	+8	+6	+3,0	0	-4	-6	+16	+10	+5	0	-4	-6	+20	+14	+39	+25	+80	+60
od 1 do 3	0	-2,0	+2	0	-3,0	-6	-10	-12	+6	0	-5	-10	-14	-16	+6	0	+14	0	+20	0
přes 3 do 6	+5	+2,5	+12	+8	+4,0	+2	-5	-9	+22	+12	+6	+3	-4	-8	+28	+18	+50	+30	+105	+75
přes 3 do 6	0	-2,5	+4	0	-4,0	-6	-13	-17	+10	+0	-6	-9	-16	-20	+10	0	+20	0	+30	0
přes 6 do 10	+6	+3,0	+14	+9	+4,5	+2	-7	-12	+28	+15	+7	+5	-4	-9	+35	+22	+61	+36	+130	+90
přes 6 do 10	0	-3,0	+5	0	-4,5	-7	-16	-21	+13	0	-7	-10	-19	-24	+13	0	+25	0	+40	0
přes 10 do 14	+8	+4,0	+17	+11	+5,5	+2	-9	-15	+34	+18	+9	+6	-5	-11	+43	+27	+75	+43	+160	+110
přes 10 do 14	0	-4,0	+6	0	-5,5	-9	-20	-26	+16	0	-9	-12	-23	-29	+16	0	+32	0	+50	0
přes 14 do 18	+8	+4,0	+17	+11	+5,5	+2	-9	-15	+34	+18	+9	+6	-5	-11	+43	+27	+75	+43	+160	+110
přes 14 do 18	0	-4,0	+6	0	-5,5	-9	-20	-26	+16	0	-9	-12	-23	-29	+16	0	+32	0	+50	0
přes 18 do 24	+9	+4,5	+20	+13	+6,5	+2	-11	-18	+41	+21	+10	+6	-7	-14	+53	+33	+92	+52	+195	+130
přes 18 do 24	0	-4,5	+7	0	-6,5	-11	-24	-31	+20	0	-10	-15	-28	-35	+20	0	+40	0	+65	0
přes 24 do 30	+9	+4,5	+20	+13	+6,5	+2	-11	-18	+41	+21	+10	+6	-7	-14	+53	+33	+92	+52	+195	+130
přes 24 do 30	0	-4,5	+7	0	-6,5	-11	-24	-31	+20	0	-10	-15	-28	-35	+20	0	+40	0	+65	0
přes 30 do 40	+11	+5,5	+25	+16	+8,0	+3	-12	-21	+50	+25	+12	+7	-8	-17	+64	+39	+112	+62	+240	+130
přes 30 do 40	0	-5,5	-9	0	-8,0	-13	-28	-37	+25	0	-12	-18	-33	-42	+25	0	+50	0	+80	0
přes 40 do 50	+11	+5,5	+25	+16	+8,0	+3	-12	-21	+50	+25	+12	+7	-8	-17	+64	+39	+112	+62	+240	+130
přes 40 do 50	0	-5,5	-9	0	-8,0	-13	-28	-37	+25	0	-12	-18	-33	-42	+25	0	+50	0	+80	0
přes 50 do 65	+13	+6,5	+29	+19	+9,5	+4	-14	-26	+60	+30	+15	+9	-9	-21	+76	+46	+134	+74	+290	+190
přes 50 do 65	0	-6,5	+10	0	-9,5	-15	-33	-45	+30	0	-15	-21	-39	-51	+30	0	+60	0	+100	0
přes 65 do 80	+13	+6,5	+29	+19	+9,5	+4	-14	-26	+60	+30	+15	+9	-9	-21	+76	+46	+134	+74	+290	+190
přes 65 do 80	0	-6,5	+10	0	-9,5	-15	-33	-45	+30	0	-15	-21	-39	-51	+30	0	+60	0	+100	0
přes 80 do 100	+15	+7,5	+34	+22	+11,0	+4	-16	-30	+71	+35	+17	+10	-10	-24	+90	+54	+159	+87	+340	+220
přes 80 do 100	0	-7,5	+12	0	-11,0	-18	-38	-52	+36	0	-17	-25	-45	-59	+36	0	+72	0	+120	0
přes 100 do 120	+15	+7,5	+34	+22	+11,0	+4	-16	-30	+71	+35	+17	+10	-10	-24	+90	+54	+159	+87	+340	+220
přes 100 do 120	0	-7,5	+12	0	-11,0	-18	-38	-52	+36	0	-17	-25	-45	-59	+36	0	+72	0	+120	0
přes 120 do 140	+18	+9,0	+39	+25	+12,5	+4	-20	-36	+83	+40	+20	+12	-12	-28	+106	+63	+185	+100	+395	+250
přes 120 do 140	0	-9,0	+14	0	-12,5	-21	-45	-61	+43	0	-20	-28	-52	-68	+43	0	+85	0	+145	0
přes 140 do 160	+18	+9,0	+39	+25	+12,5	+4	-20	-36	+83	+40	+20	+12	-12	-28	+106	+63	+185	+100	+395	+250
přes 140 do 160	0	-9,0	+14	0	-12,5	-21	-45	-61	+43	0	-20	-28	-52	-68	+43	0	+85	0	+145	0
přes 160 do 180	+18	+9,0	+39	+25	+12,5	+4	-20	-36	+83	+40	+20	+12	-12	-28	+106	+63	+185	+100	+395	+250
přes 160 do 180	0	-9,0	+14	0	-12,5	-21	-45	-61	+43	0	-20	-28	-52	-68	+43	0	+85	0	+145	0
přes 180 do 200	+20	+10	+44	+29	+14,5	+5	-22	-41	+96	+46	+23	+13	-14	-33	+122	+72	+215	+115	+460	+290
přes 180 do 200	0	-10	+15	0	-14,5	-24	-51	-71	+50	0	-23	-33	-60	-79	+50	0	+100	0	+170	0
přes 200 do 225	+20	+10	+44	+29	+14,5	+5	-22	-41	+96	+46	+23	+13	-14	-33	+122	+72	+215	+115	+460	+290
přes 200 do 225	0	-10	+15	0	-14,5	-24	-51	-71	+50	0	-23	-33	-60	-79	+50	0	+100	0	+170	0
přes 225 do 250	+20	+10	+44	+29	+14,5	+5	-22	-41	+96	+46	+23	+13	-14	-33	+122	+72	+215	+115	+460	+290
přes 225 do 250	0	-10	+15	0	-14,5	-24	-51	-71	+50	0	-23	-33	-60	-79	+50	0	+100	0	+170	0
přes 250 do 280	+23	+11,5	+49	+32	+16	+5	-25	-47	+108	+52	+26	+16	-14	-36	+137	+81	+240	+130	+510	+320
přes 250 do 280	0	-11,5	+17	+	-16	-27	-57	-79	+56	0	-26	-36	-66	-88	+56	0	+110	0	+190	0
přes 280 do 315	+23	+11,5	+49	+32	+16	+5	-25	-47	+108	+52	+26	+16	-14	-36	+137	+81	+240	+130	+510	+320
přes 280 do 315	0	-11,5	+17	+	-16	-27	-57	-79	+56	0	-26	-36	-66	-88	+56	0	+110	0	+190	0
přes 315 do 355	+25	+12,5	+54	+36	+18	+7	-26	-51	+119	+57	+28	+17	-16	-41	+151	+89	+265	+140	+570	+360
přes 315 do 355	0	-12,5	+18	0	-18	-29	-62	-87	+62	0	-28	-40	-73	-98	+62	0	+125	0	+210	0
přes 355 do 400	+25	+12,5	+54	+36	+18	+7	-26	-51	+119	+57	+28	+17	-16	-41	+151	+89	+265	+140	+570	+360
přes 355 do 400	0	-12,5	+18	0	-18	-29	-62	-87	+62	0	-28	-40	-73	-98	+62	0	+125	0	+210	0
přes 400 do 450	+27	+13,5	+60	+40	+20	+8	-27	-55	+131	+63	+31	+18	-17	-45	+165	+97	+290	+155	+630	+400
přes 400 do 450	0	-13,5	+20	0	-20	-32	-67	-95	+68	0	-31	-45	-80	-108	+68	0	+135	0	+230	0
přes 450 do 500	+27	+13,5	+60	+40	+20	+8	-27	-55	+131	+63	+31	+18	-17	-45	+165	+97	+290	+155	+630	+400
přes 450 do 500	0	-13,5	+20	0	-20	-32	-67	-95	+68	0	-31	-45	-80	-108	+68	0	+135	0	+230	0

Toleranční pole v prvním řádku jsou přednostní.